

Version: 3.2.1 Date: May. 2004

New Feature:

1.) Support “constant touch” for Windows 9X/NT4/ME/2000/XP.

Driver does not report mouse movement event for constant touch when “constant touch” function was activated.

2.) Support Auto-Right button. For Windows 9X/NT4/ME/2000/XP.

Driver will report a “right click” mouse event after lift-up from a constant touch if the “Auto-Right button” function was enabled.

3.) Enable/disable the pop-up one point calibration utility.

Touchkit utility allows user to enable/disable the pop-up one point calibration utility when the display was rotated by 90 degrees.

Bug Fix:

1.) Fix the bug that the system will be hanged during driver installation when the system has built-in software modem which creates virtual COM port in Windows OS.

2.) Fix the bug that Touchkit utility reports exception error on some motherboards which has many on board COM ports share same IRQ in Windows 2000/XP.

3.) Fix the bug that touch accuracy lost when multi-monitor function enabled and the secondary monitors are located at upper or left side of the primary monitor in Windows OS.